




State of Ohio Environmental Protection Agency

Northeast District Office

2110 E. Aurora Road
Twinsburg, Ohio 44087
(216) 425-9171



Richard F. Celeste
Governor

June 9, 1989

RE: OHIO EPA PERMIT NO. 3ID00021*DD
NPDES PERMIT NO. OH0004219

Mr. William Lacure
Environmental Control Coordinator
The Timken Company
1835 Deuber Avenue
Canton, Ohio 44706

Dear Mr. Lacure:

We are in receipt of your self-monitoring report covering the month of April 1989 for the referenced facility. Our review indicates violations of the conditions of your NPDES permit. The specific instances of noncompliance are as follows:

<u>OUTFALL</u>	<u>DATE</u>	<u>PARAMETER</u>	<u>REPORTED</u>	<u>UNITS</u>	<u>PERMIT LIMITATION</u>
007	4/3/89	Ph	9.3	S.U.	9.0 (max)
015	4/3,10,17,24/89	Zinc	Up to 640	ug/l	365 (max)
015	4/24/89	Zinc	10.39	kg/day	9.97 (max)
015	--	Zinc	8.20	kg/day	5.15 (avg)

Please be advised that failure to comply with the effluent limitations or to satisfy the monitoring or reporting requirements of your NPDES permit may be cause for enforcement action pursuant to the Ohio Revised Code Chapter 6111.

If there are any questions, please contact this office.

Sincerely,

Kelvin F. Rogers
Environmental Scientist
Division of Water Pollution Control

KFR:mjo

cc: R. Phelps, DWPC, CO